











 Ø6,3x50 mm A1 x 32	 4 mm A3 x 1	 Ø4x16 mm D1 x 36	 Ø4,2x25 mm D2 x 6	 Ø4x30 mm D3 x 6
 Ø1,6x20 mm F x 54	 Ø8x36 mm G x 84	 H x 3	 K x 3	 Ø15 mm N x 6
 50g R x 1				




Box 1


390x398x3 mm




120x400x16 mm




253x413x16 mm




120x360x16 mm




418x1378x16 mm




120x360x16 mm




60x418x16 mm



260x418x16 mm




120x400x16 mm




Fittings & Tools

Box


270x418x16 mm




856x1378x16 mm




856x1378x16 mm




418x450x16 mm




418x810x16 mm





70x418x16 mm





418x630x16 mm







1



2





3






4

G x 8




5

- A1 x 30
- A3 x 1
- D1 x 18
- G x 38
- K.1 x 3
- K.2 x 3
- N x 6





6




G x 24





R x 1




7



F x 54



! $XX=YY \cong 90^\circ$



x 3

8





D1 x 18



K.3 x 3




K.4 x 3






x 3

9



G x 6




x 3



10



D2 x 6



H x 3





x 3

11



D3 x 6



x 3

12

