












 Ø6,3x50 mm A1 x 8	 Ø12 mm A2 x 8	 4 mm A3 x 1	 Ø3x16 mm D1 x 20	 Ø4x16 mm D2 x 8
 Ø8x30 mm E x 2	 Ø1,6x25 mm F x 16	 Ø8x36 mm G x 4	 M x 4	 N x 4
 U x 4	 Y x 2			




Box

450x699x16 mm




1 x1

450x699x16 mm



2 x1

800x450x16 mm



3 x1

768x80x16 mm



4 x1

200x200x3 mm




5 x2

768x80x16 mm









7 x1

Fittings & Tools







N x4



1






2








3



⚠ XX=YY≅90°







4



5





D1 x 4

Y x 2




i

D2 x 4








Ex 2



Ø8



1



2

